

FIG.1 (PRIOR ART)




FIG.2 (PRIOR ART)




FIG.3 (PRIOR ART)




FIG.4A (PRIOR ART)





FIG.4B (PRIOR ART)






FIG.6A




FIG.6B




FIG.7A




FIG.7B




FIG.8




FIG.9A




FIG.9B

β	\			
	a=3/4 b=1/4	a=7/8 b=1/8	a=15/16 b=1/16	
T _{B2}	S=0	S=0	S=0	
·p2	a=1/2 b=1/2	a=3/4 b=1/4	a=7/8 b=1/8	
Т _{в1}	S=1	S=1	S=1	
·β1	a=1/4	a=1/2	a=3/4	
	b=3/4 S=1	b=1/2 S=1	b=1/4 S=1	
	$T_{\alpha 1}$ $T_{\alpha 2}$		α2	$\stackrel{\blacktriangleright}{\alpha}$

FIG.10





FIG.11






FIG.13

